

To: Jackson, Hylton[hylton.jackson@dnr.iowa.gov]
From: Howell, Tonya
Sent: Thur 10/19/2017 7:33:38 PM
Subject: RE: DICO Photos

Hey, everything helps. I appreciate the effort. Did you have anything inside the buildings or of the south pond?

Tonya Howell

Remedial Project Manager

Superfund Redevelopment Initiative Coordinator

SUPR/FFPC

913-551-7589

From: Jackson, Hylton [mailto:hylton.jackson@dnr.iowa.gov]
Sent: Thursday, October 19, 2017 2:27 PM
To: Howell, Tonya <Howell.Tonya@epa.gov>
Subject: DICO Photos

This was hardly worth the wait

One of the SE corner of the office building

One of the E side of Building 1 (to the right) and the NE corner of Building 2 on the left.


One of the W side of the Production Bld. from the SW corner

One of the NW corner of the site - looking SE

One of the S side of Bld. 3 (background) and the Maintenance Bld pad in the foreground

--

Hylton Jackson | Environmental Specialist



Iowa Department of Natural Resources

P 515-725-8338 | F 515-725-8201 | 502 E. 9th St., Des Moines, IA 50319

www.iowadnr.gov